

Western Region

BULLETIN NO. 14



C_{AR}

L_{OCATION}

I_{DENTITY}

C_{ODES}

Instructions - Maps
Mojave & Bakersfield
Subdivisions

Mainline / S.P. Joint

Zones 01, 08, 65, 66, 71 - 76

Revised March 1991

WESTERN REGION CLIC BOOK ASSIGNMENTS AS OF SEPT 1990

| CLIC BULLETIN NO. | TERRITORY COVERED |
|-------------------|---|
| 1 | Cadiz-Needles-Ripley, Including Barstow Yard Tracks 0101-0165. Zones 50-52, 57-64, 66-74. |
| 2 | Lucerne Valley and Cajon Subs, Plus S.B. "A" YD Zones 02, 82-84. |
| 3 | S.B. Yards and Redlands Sub. Zones 01-05+83. |
| 4 | Pasadena Sub. Zones 13-17, 21+91 |
| 5 | S.B. and Pasadena Subs. Zones 17-25. |
| 6 | S.B. Sub/Highgrove-Esperanza and San Jac Sub. Zones 30, 31+43. |
| 7 | Fullerton and Santa Ana, Zones 67, 69-72, 74-77, 81, 85-89+92. |
| 8 | S.B. Sub, LA Area, Zones 33-35, 37-39, 44-47. |
| 9 | S.B. Sub, LA Area, Zones 48-56. |
| 10 | S.B. Sub, LA Area, Zones 57-70. |
| 11 | Harbor Sub, Zones 29-32. |
| 12 | Harbor Sub, Zones 07-12. |
| 13 | San Diego and Escondido Subs, Zones 40-42, 46, 48-50, 78, 79+98. |
| 14 | Mojave and Bakersf Subs, Mainline SP Joint, Zones 01,08,65,66,71-76. |
| 15 | Bakersf, Arvin, Oil City Subs and Sunset Rly, Zones 01-05,09,11-14, 18+19. |
| 16 | Porterville, Visalia Subs, Including Oil Jct To Ducor, Zones 11,14,20-29+36. |
| 17 | Calwa-Fresno Industries, Fresno Interurban, Zones 51,52,55,57-59. |
| 18 | Stockton Sub, Zones 04-06,13,77-79. |
| 19 | Stockton-Mormon, Zones 01-03,79+89. |
| 20 | Richm, Oakland, S.F. Zones 01-11+23. |
| 21 Final | Barstow Yards, Zones 01, 10-18. |

CAR LOCATION IDENTITY CODES

This booklet contains instructions and maps for the Car Location Identity Code (CLIC) and procedures governing the Work Order Document System.

Maps are not drawn to scale and are to be used only as a guide to locating customer and yard tracks and the numbers assigned to them.

The geographical area covered in this booklet is divided into zones. Each zone has designated tracks and/or industries within its boundary.

A CLIC number will consist of six digits-the first two digits designate the zone; the second two digits indicate the track number within the zone; the last two digits represent the actual spot along the track.

The combination of the zone-track-spot number is known as the "Car Location Identity Code" (CLIC) System.

This "CLIC" number will be used for switching and reporting purposes rather than the industry or track name.

****EXAMPLE OF CLIC NUMBER****

```

01   20   04   __ Spot Number
                _____ Track Number
                _____ Zone Number
    
```

All switch targets or stands have been painted with a combination of the zone and track number.

Spot numbers have been painted on doors, docks, buildings, gates, etc., wherever possible.

WORK ORDER DOCUMENT

Any written or verbal instructions issued to yard or road crews requiring work to be performed during their tour of duty will constitute a work order.

NOTE: Exceptions to written work orders must be noted on the work orders according to current instructions; cars handled on verbal work orders must be reported on the prescribed form.

Conductors and Engine Foremen will be furnished work orders during their tour of duty.

This document will specify the cars to be picked up or set out at various stations, industries or interchange tracks served by the train or switch job.

Certain information (described below) must be recorded on the work order document by the Conductor or Engine Foreman. Prior to turning in the document at the designated reporting station, it must be dated and signed—even if no work was accomplished. This is necessary to comply with switching and demurrage tariffs, as well as other rules and regulations.

Conductors and Engine Foreman must show on work order cars handled, time and date work performed, CLIC number taken from, CLIC number left and appropriate code as listed below:

BO - Bad order
ND - Work indicated not done (State reason.)
NIT - Car not in train or not on track
OTCC- Car on track, carriers convenience
OTNP- Car on track not placed (State reason.)
PULL- Car pulled, time and date
SPOT- Car spotted, time and date

Conductor/Engine Foreman must make notation on work order and notify the appropriate employe (S/O, RYO clerk, Dispatcher) of any exceptions taken to the work order, such as no car, car not on list, car out of line, car is hazardous, excess dimension (when the information is not so indicated on work order), car is carded rear or head end movement, or any other exceptions noted.

If switching is performed without a work order, the Conductor or Engine Foreman must complete the prescribed form showing all the information required above and turn it in at the designated reporting station.

If an industry requests service not shown on work order, Conductor/Engine Foreman should obtain such request in writing. This request is to be turned in with work order for processing. If unable to obtain request in writing, Conductor/Engine Foreman should record on work order the name of person making request and the service requested and performed.

For observation and guidance, the following codes may appear on work order.

AI - Agri. Industries
BI - Bad Order
BA - Blasting Agent (Hazardous)
CG - Cargill
CD - Condemned
CB - Combustible (Hazardous)
CL - Chlorine (Hazardous)
CM - Corrosive (Hazardous)
DG - Dangerous
DH - Do Not Hump
DU - Do Not Uncouple
EQ - Equity Export - Houston
FG - Flammable Gas (Hazardous)
FL - Flammable (Hazardous)
FS - Flammable Solid (Hazardous)
FW - Flam. Solid W (Dangerous When Wet)
HE - Head End Only
HL - High Wide Load
PE - Houston Public Elevator
HV - High Value
IP - Interchange Prohibited
IPSW - Intraplant Switch (Respot Car)
MR - Mech. Refrig. Maintain - Degrees
MCNR - Mech. Car or Trailer - No Refrigeration Required
NG - Non-Flammable Gas (Hazardous)
NP - No Placards Required
OM - Oxidizer (Hazardous)
OP - Organic Peroxide (Hazardous)
OR - Other Regulated Material
OX - Oxygen
PA - Poison Gas (Hazardous)
PB - Poison
RE - Rear End Only
RM - Radioactive Material
REJT - Car Rejected by Shipper
RSPT - Respot Due to Railroad Error
TURN - Turn Car & Respot
WH - Weight Heavy
WI - Waive Inspection - Set Direct
WL - Weigh Light
XA - Explosive "A"
XB - Explosive "B"
XX - DO NOT MOVE THIS CAR

6510 Hinkley Siding
6511 Back Track
6520 Jim Grey Siding
6521 Team Track
6530 Boron Siding
6556 No. 3 Storage
6582 Spur #18
6531 Team Track
6557 No. 4 Storage
6583 Spur #1
6532 Boron House Track
6558 No. 5 Storage
6584 Spur #5
6533 US Borax New Yd Track 6
6560 Boric Acid Plant
6585 Spur #4
6534 US Borax New Yd Track 5
6561 A-Track
6586 Spur #3
6535 US Borax New Yd Track 4
6562 C-Track
6587 Spur #2
6536 US Borax New Yd Track 3
6563 Boric Acid Plant
6588 Spur #6 (Runaround)
6537 US Borax New Yd Track 2
6565 Boric Acid Plant
6589 Spur #8
6538 US Borax New Yd Track 1
6566 Pit
6590 Spur #7
6540 US Borax Mine Spur
6567 E-Track
6591 Spur #17
6542 Old Scale Track
6568 Acid Track
6592 Spur #9 Helium Spot)
6544 R/A Plant Spur
6569 D-Track
6593 Spur #10 Helium Spot)
6545 Acid Spur
6570 B-2
6594 Spur #11
6546 Pit Track
6571 B-3
6595 Spur #12
6547 Mill Track
6575 Rocket Base Spur
6596 Spur #15
6548 Kitchen Track
6576 Mud Spur
6597 Spur #16
6550 B-I
6577 Rocket Base/USAF
6598 Spur #14
6551 Western Spur

6578 Spur "zero"
6599 Spur #13
6554 No. 1 Storage
6579 Spur #20
6555 No. 2 Storage
6580 Spur #21
6581 Spur #19
6601 Silt Siding
6602 Back Track
6605 Edwards Siding
6606 Edwards House track
6607 East Leg of Wye
6608 West Leg of Wye
6609 Tail of Wye
6610 Runaround
6611 West Leg Govt. Wye
6612 East Leg Govt. Wye
6613 Tail Govt. Wye
6614 Unconventional Fuel Stge. #14
6615 Unconventional Fuel Stge. #11
6616 Conventional Fuel Stge.
6617 G. E. Fuel Unloading
6618 Warehouse track #3
6619 Warehouse track #2
6620 Warehouse track #1
6630 Bissell Siding
6631 Back Track
6640 Sanborn Siding
6641 Back Track
0101 SP Interchange Track
0801 Set Out Track
0802 Set Out Track
0803 Bad Order Set Out Track
0812 SF Team Track Mojave
0804 Set Out Track
0806 Monolith Portland Cement
0807 Monolith Portland Cement
0808 Monolith Portland Cement
0809 Monolith Portland Cement
0811 Monolith Middle Track
0815 Siding
0816 Set Out Track
0817 East Leg of Wye
0818 West Leg of Wye
0822 Lime Siding
0823 Team Track
0824 Storage
0826 Set Out Track
0827 Siding
0831 Set Out Track
0836 Set Out Track
0840 Set Out Track
0845 Set Out Track
0851 Set Out Track
0855 Set Out Track
0857 Set Out Track
0865 Siding

0866 Set Out Track
0874 Vacant
0875 Vacant
0877 Vacant
0879 Helper Spur
0102 Texaco Refmar
0103 Texaco Refmar
0104 Texaco Refmar
0105 Vacant
0106 Texaco Refmar
0107 Vacant
0109 Texaco Refmar
0110 Out of Service
0111 Sunland Refinery
0113 P G and E
0114 P G and E
0122 Landco Siding
0123 Lufkin Ind.
0124 Asbury Transport
7115 Storage Track
7116 IFFCO
7117 IFFCO
7121 Runaround
7201 Passing Track
724190 Storage
7202 Storage #3
724290 Storage
7203 Storage #4
724301-03 Pennwalt Drill
7204 Storage #5
724401-03 Pennwalt Corp. Ag-Chem-Decco
720501-04 Brown & Bryant
7207 Storage #1
724501-04 Shed-6-Drill
7220 Lead Track
724601-04 Shed-6
7221 Vacant
724701-03 Shed-5 Drill
7222 Vacant
724801-03 Heart of Texax Sand
7223 Vacant
724990 Storage
722402-04 Handel Drill 2
725001-04 Shafter Grain Drill
722502-04 Handel Drill 1
725101-04 Shafter Grain
722602-04 W. C. Handel 2-A
725104-08 Vacant
722701 Miracle Feed
725201-03 Vacant
722890 Storage
725301-03 Vacant
722990 Storage
725490 Storage-Drill
723001-05 Vacant
725590 Storage-Drill


723101-05 General Potato
7240 Lead Track
7201 Passing Track
726901-08 Vacant Drill
7202 Storage #3
727001 Grain Elevator
721099 Team Track #1
721199 Team Track #2
7256 Drill
7257 Storage
7258 Vacant
725901-04 Polychemical
7260 Vacant
7261 Vacant
7262 Vacant
7263 Vacant
726401-07 Wong Sill
726501-07 Wong Sill
726601-07 Wong Sill
726701-08 Northern Mud Drill
726801-08 Northern Mud Drill
7303 Passing Track
7304 Pryopaco
7305 Pyropaco
7304 Middle #1
7328 Vacant
7306 Savage Coal
7329 Vacant
7307 Middle #2
7331 Bean House
7308 Savage Coal
7332 Storage
7309 Savage Coal
7333 Storage
7310 Savage Coal
7334 Vacant
731101-04 Vacant
7335 San Juan Crops
731105-07 Vacant
7336 San Juan Crops
731108-11 E. J. Peters
7337 Vacant
731112-17 Vacant
7338 Vacant
7315 Storage
7339 Vacant
7316 Standard
7340 Vacant
7317 Richfield
7341 Vacant
7318 Storage
7342 Vacant
7319 Maple Grain Elevator
7343 Vacant
7320 Team Track
7344 Vacant
7321 Team Track

7345 Vacant
7322 Team Track
7346 Vacant
7325 Sandoz
7347 Vacant
7401 Passing Track
7402 Superior Gypsum
7421 Passing Track
742201-04 Sandrini Bros.
742390 Storage
7431 Passing Track
7441 Stoil Storage Track
7442 Alpaugh Main Line
7443 Runaround - Western Farm Storage
(Leased)
744401-08 Western Farm Stge (leased)
744501-08 Western Farm Svc.-W. Isle
7483 Angiola Passing Track
7484 South Lake Farms
7488 Blanco Storage
7502 J. G. Boswell Co.
7532 West Leg of Wye
7503 J. G. Boswell Co.
7534 West Team Track
7506 East Siding Track
7535 House Track
7507 Salyer American
7538 Star Craft
7509 Salyer American
7540 Frye Copy Systems
7511 Central Valley
7541 Outfit Track
7513 J. G. Boswell Gin Track
7542 Old Sugar Mill
7514 J. G. Boswell
7543 Farr Co.
7517 Vacant
751904-05 Corcoran Milling
7520 Middle Track
7522 J. G. Boswell Storage
7524 Coast Grain
7525 Company Matl & Team
7526 Back Team Track
7528 J. G. Boswell Seed Cleaning
7530 Vacant
7531 East Leg of Wye
7605 Guernsey Siding
7611 Siding
7612 Ashland Chemical
7615 Contadina
7620 Old Runaround
7621 Storage
7623 Armstrong-Drill
7624 Armstrong-House
7627 New Runaround
763001-10 Calcot


763101-05 Calcot
7633 Verdegbrothe
7634 Verdegbrothe Runaround
7635 Actagrterminal
7636 Liquid Chemical
7636 Occidental Chemical
7637 Chase Bag
7638 Armco
7639 Chase Bag
7640 Standard Register
7642 Sanchez & Sanchez
7644 Hanford East Siding
7646 Vacant
764701 Snow Commodities
764794 Penny-Newman
7648 Beacon Oil
7649 Beacon Stub Track
7651 Turano Team #1
7652 Beacon Oil
7653 Turano Team #2
7655 Hanford West Siding
7657 Back Track
7664 Hanford Team
7666 Vacant
7667 Shirley Siding
7668 Verdegaa1 Brothers
7669 Runaround
7670 Storage
7671 Conejo Siding
7672 Storage
7673 Harris Feeding
767494 Sierra Valley
7676 Vie Del Storage
767701-12 Vie Del Winery
7680 Bowles Siding
7681 Storage
768294 Cal Gas
768301-04 Fowler Packing

6510 Hinkley Siding
6511 Back Track
6520 Jim Grey Siding
6521 Team Track

-1-




| | | | | | |
|------|-------------------------|------|------------------|------|-----------------------|
| 6530 | Boron Siding | 6556 | No. 3 Storage | 6581 | Spur #19 |
| 6531 | Team Track | 6557 | No. 4 Storage | 6582 | Spur #18 |
| 6532 | Boron House Track | 6558 | No. 5 Storage | 6583 | Spur #1 |
| 6533 | US Borax New Yd Track 6 | 6560 | Boric Acid Plant | 6584 | Spur #5 |
| 6534 | US Borax New Yd Track 5 | 6561 | A-Track | 6585 | Spur #4 |
| 6535 | US Borax New Yd Track 4 | 6562 | C-Track | 6586 | Spur #3 |
| 6536 | US Borax New Yd Track 3 | 6563 | Boric Acid Plant | 6587 | Spur #2 |
| 6537 | US Borax New Yd Track 2 | 6565 | Boric Acid Plant | 6588 | Spur #6 (Runaround) |
| 6538 | US Borax New Yd Track 1 | 6566 | Pit | 6589 | Spur #8 |
| 6540 | US Borax Mine Spur | 6567 | E-Track | 6590 | Spur #7 |
| 6542 | Old Scale Track | 6568 | Acid Track | 6591 | Spur #17 |
| 6544 | R/A Plant Spur | 6569 | D-Track | 6592 | Spur #9 Helium Spot) |
| 6545 | Acid Spur | 6570 | B-2 | 6593 | Spur #10 Helium Spot) |
| 6546 | Pit Track | 6571 | B-3 | 6594 | Spur #11 |
| 6547 | Mill Track | 6575 | Rocket Base Spur | 6595 | Spur #12 |
| 6548 | Kitchen Track | 6576 | Mud Spur | 6596 | Spur #15 |
| 6550 | B-I | 6577 | Rocket Base/USAF | 6597 | Spur #16 |
| 6551 | Western Spur | 6578 | Spur "zero" | 6598 | Spur #14 |
| 6554 | No. 1 Storage | 6579 | Spur #20 | 6599 | Spur #13 |
| 6555 | No. 2 Storage | 6580 | Spur #21 | | |



- 6601 Silt Siding
- 6602 Back Track
- 6605 Edwards Siding
- 6606 Edwards House track
- 6607 East Leg of Wye
- 6608 West Leg of Wye
- 6609 Tail of Wye
- 6610 Runaround
- 6611 West Leg Govt. Wye
- 6612 East Leg Govt. Wye
- 6613 Tail Govt. Wye
- 6614 Unconventional Fuel Stge. #14
- 6615 Unconventional Fuel Stge. #11
- 6616 Conventional Fuel Stge.
- 6617 G. E. Fuel Unloading
- 6618 Warehouse track #3
- 6619 Warehouse track #2
- 6620 Warehouse track #1


-5-



6630 Bissell Siding
 6631 Back Track
 6640 Sanborn Siding
 6641 Back Track

-7-


C.E.No.12172-SK Engineering Services--Tapeka 3/91



ZONE 66


SP YARD TRACKS NOT LISTED INTENTIONALLY

- 0101 SP Interchange Track
- 0801 Set Out Track
- 0802 Set Out Track
- 0803 Bad Order Set Out Track
- 0812 SF Team Track Mojave




- 0804 Set Out Track
- 0806 Monolith Portland Cement
- 0807 Monolith Portland Cement
- 0808 Monolith Portland Cement
- 0809 Monolith Portland Cement
- 0811 Monolith Middle Track

-11-




- 0815 Siding
- 0816 Set Out Track
- 0817 East Leg of Wye
- 0818 West Leg of Wye
- 0822 Lime Siding
- 0823 Team Track
- 0824 Storage
- 0826 Set Out Track
- 0827 Siding
- 0831 Set Out Track



0836
0840

Set Out Track
Set Out Track


-15-



0845
0851

Set Out Track
Set Out Track


-17-



0855
0857

Set Out Track
Set Out Track

-19-




0865
0866

Siding
Set Out Track

-21-

C.E.No.12172--SK Engineering Services--Topeka 3/91




22

ZONE 08

0874 Vacant
 0875 Vacant
 0877 Vacant
 0879 Helper Spur


-23-

C.E.No.12172-SK Engineering Services--Topeka 3/91



| | |
|------|------------------|
| 0102 | Texaco Refmar |
| 0103 | Texaco Refmar |
| 0104 | Texaco Refmar |
| 0105 | Vacant |
| 0106 | Texaco Refmar |
| 0107 | Vacant |
| 0109 | Texaco Refmar |
| 0110 | Out of Service |
| 0111 | Sunland Refinery |
| 0113 | P G and E |
| 0114 | P G and E |
| 0122 | Landco Siding |
| 0123 | Lufkin Ind. |
| 0124 | Asbury Transport |


-25-




7115 Storage Track
7116 IFFCO
7117 IFFCO

-27-


C.E.No.12172-SK Engineering Services-Topoka 3/91



C.E.No.12172-SK Engineering Services-Topoka 3/91




| | | | |
|-----------|------------------|-----------|---------------------|
| 7201 | Passing Track | 724190 | Storage |
| 7202 | Storage #3 | 724290 | Storage |
| 7203 | Storage #4 | 724301-03 | Pennwalt Drill |
| 7204 | Storage #5 | 724401-03 | Pennwalt Corp. |
| 720501-04 | Brown & Bryant | | Ag-Chem-Decco |
| 7207 | Storage #1 | 724501-04 | Shed-6-Drill |
| 7220 | Lead Track | 724601-04 | Shed-6 |
| 7221 | Vacant | 724701-03 | Shed-5 Drill |
| 7222 | Vacant | 724801-03 | Heart of Texax Sand |
| 7223 | Vacant | 724990 | Storage |
| 722402-04 | Handel Drill 2 | 725001-04 | Shafter Grain Drill |
| 722502-04 | Handel Drill 1 | 725101-04 | Shafter Grain |
| 722602-04 | W. C. Handel 2-A | 725104-08 | Vacant |
| 722701 | Miracle Feed | 725201-03 | Vacant |
| 722890 | Storage | 725301-03 | Vacant |
| 722990 | Storage | 725490 | Storage-Drill |
| 723001-05 | Vacant | 725590 | Storage-Drill |
| 723101-05 | General Potato | | |
| 7240 | Lead Track | | |



| | | | |
|-----------|--------------------|-----------|----------------|
| 7201 | Passing Track | 726901-08 | Vacant Drill |
| 7202 | Storage #3 | 727001 | Grain Elevator |
| 721099 | Team Track #1 | | |
| 721199 | Team Track #2 | | |
| 7256 | Drill | | |
| 7257 | Storage | | |
| 7258 | Vacant | | |
| 725901-04 | Polychemical | | |
| 7260 | Vacant | | |
| 7261 | Vacant | | |
| 7262 | Vacant | | |
| 7263 | Vacant | | |
| 726401-07 | Wong Sill | | |
| 726501-07 | Wong Sill | | |
| 726601-07 | Wong Sill | | |
| 726701-08 | Northern Mud Drill | | |
| 726801-08 | Northern Mud Drill | | |


-33-



7303
7304
7305

Passing Track
Pryopaco
Pyropaco


-35-



7401
7402


Passing Track
Superior Gypsum

-39-




7421 Passing Track
742201-04 Sandrini Bros.
742390 Storage
7431 Passing Track

-41-



- 7441 Stoil Storage Track
- 7442 Alpaugh Main Line
- 7443 Runaround - Western Farm Storage (Leased)
- 744401-08 Western Farm Stge (Leased)
- 744501-08 Western Farm Svc.-W. Isle


-43-



7483
7484
7488

Angiola Passing Track
South Lake Farms
Blanco Storage


-45-




| | | | |
|-----------|-----------------------------|------|-------------------|
| 7502 | J. G. Boswell Co. | 7532 | West Leg of Wye |
| 7503 | J. G. Boswell Co. | 7534 | West Team Track |
| 7506 | East Siding Track | 7535 | House Track |
| 7507 | Salyer American | 7538 | Star Craft |
| 7509 | Salyer American | 7540 | Frye Copy Systems |
| 7511 | Central Valley | 7541 | Outfit Track |
| 7513 | J. G. Boswell Gin Track | 7542 | Old Sugar Mill |
| 7514 | J. G. Boswell | 7543 | Farr Co. |
| 7517 | Vacant | | |
| 751904-05 | Corcoran Milling | | |
| 7520 | Middle Track | | |
| 7522 | J. G. Boswell Storage | | |
| 7524 | Coast Grain | | |
| 7525 | Company Matl & Team | | |
| 7526 | Back Team Track | | |
| 7528 | J. G. Boswell Seed Cleaning | | |
| 7530 | Vacant | | |
| 7531 | East Leg of Wye | | |

-47-

C.E.No.12173-SK Engineering Services-Topoka 3/91




| | |
|-----------|------------------------|
| 7605 | Guernsey Siding |
| 7611 | Siding |
| 7612 | Ashland Chemical |
| 7615 | Contadina |
| 7620 | Old Runaround |
| 7621 | Storage |
| 7623 | Armstrong-Drill |
| 7624 | Armstrong-House |
| 7627 | New Runaround |
| 763001-10 | Calcot |
| 763101-05 | Calcot |
| 7633 | Verdegbrothe |
| 7634 | Verdegbrothe Runaround |
| 7635 | Actagrterminal |
| 7636 | Liquid Chemical |
| 7636 | Occidental Chemical |
| 7637 | Chase Bag |
| 7638 | Armco |
| 7639 | Chase Bag |
| 7640 | Standard Register |




| | |
|--------|---------------------|
| 7642 | Sanchez & Sanchez |
| 7644 | Hanford East Siding |
| 7646 | Vacant |
| 764701 | Snow Commodities |
| 764794 | Penny-Newman |
| 7648 | Beacon Oil |
| 7649 | Beacon Stub Track |
| 7651 | Turano Team #1 |
| 7652 | Beacon Oil |
| 7653 | Turano Team #2 |
| 7655 | Hanford West Siding |
| 7657 | Back Track |
| 7664 | Hanford Team |
| 7666 | Vacant |
| 7667 | Shirley Siding |
| 7668 | Verdegaal Brothers |

-51-



7669 Runaround
 7670 Storage
 7671 Conejo Siding
 7672 Storage
 7673 Harris Feeding
 767494 Sierra Valley
 7676 Vie Del Storage
 767701-12 Vie Del Winery



7680 Bowles Siding
7681 Storage
768294 Cal Gas
768301-04 Fowler Packing

-55-

